

Subject: Brake Fluid Exchanger BF-12 code MM: 007935016730.


Incorrect work tools to exchange brake fluid in a car. Issue with no vacuum and not to moving fluid out of cylinder to car.




The reason for running may be a damaged or worn rubber membrane inside the tank.
Below are the comparative results for the new membrane.



After opening the device, the damaged membrane looks as follows:



Properly seating of membrane inside should be looks like on picture below:



The membrane is available as a spare part in the Magneti Marelli offer under the code: 7935016910

More information can be obtained from:

Marek Tabaszewski

marek.tabaszewski@external.magnetimarelli.com

Tel. +48 664 095 718

Krystian Marczewski

krystian.marczewski@magnetimarelli.com

Tel. +48 668 686 120



Magneti Marelli Aftermarket Sp. z o.o.
Plac Pod Lipami 5
40-476 Katowice – Polska
Tel. +48 32 603 61 07 - Fax. +48 32 603 61 08
www.rgz-magnetimarelli.pl