Termometer

007950024030

Operation description:

♦ [ON/OFF]:Press the key turn on the thermometer then enter into measuring mode.

♦ [SET]: Press the key to enter into setting alarm mode.

♦ [ADJ] and [OK]: In the mode of temperature display (display °C), "HI" and high temperature alarm flash meaning in the setting of high temperature alarm. Press [ADJ] for 2 seconds to add 1°C to the high temperature alarm. When it higher than 300 °C will back to the temperature of higher 1°C than low alarm temperature. When adjusting the temperature to the required high temperature alarm press [OK] to confirm; "Lo" and low temperature alarm flash meaning in the setting of low temperature alarm. Following the above steps to set the required low temperature alarm then press [OK] to confirm. When finishing the alarm setting "Hi" or "Lo" disappears and "AL" appears meaning in the mode of alarm.

♦ [AC]: Press the key to cancel alarm and enter into the mode of measuring. "AL" disappears.